



# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Thakus	Amit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Property Management Company
<b>Address:</b>							
<b>Business name:</b>	Moreland Properties				<b>Phone:</b>		

## Medical Responses

Last name	First name	Age	Gender	Address	Apt	City

## Outside Agencies on Scene

### Police / Ambulance / OFM Details

EMS on scene	After	EMS arrival time	2022/08/18 00:00:00	EMS unit number	968
Police on scene	After	Police arrival time	2022/08/18 00:00:00	Police badge number	10542
Police organization	Toronto Police Services				
OFM contacted	No				
Pictures taken	No	Prevention remarks	<input type="checkbox"/>		

### Other Agencies Notified

Ont. Min. of Environment	<input type="checkbox"/>	Cdn. Transport Emerg. Ctr	<input type="checkbox"/>	Ont. Provincial Police	<input type="checkbox"/>
Emergency Measures	<input type="checkbox"/>	Municipal Health Unit	<input checked="" type="checkbox"/>	Ont. Ministry of Labour	<input type="checkbox"/>
Municipal Building Office	<input type="checkbox"/>	Electrical Safety Authority	<input type="checkbox"/>	Municipal Police	<input checked="" type="checkbox"/>
Tech. Safety and Stds. Assoc.	<input type="checkbox"/>	Gas Utility	<input checked="" type="checkbox"/>	Hydro Utility	<input checked="" type="checkbox"/>
		Other	<input type="checkbox"/>		

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

## Structure Fire / Explosion & Vehicle Incident Fire / Explosion

### Fire / Explosion Details

Status on Arrival (2) Fire with no evidence from street

# of Exposures 0

Area of Origin (55) Mechanical/Electrical Services Room

Possible Cause (52) Electrical Failure

Ignition source (20) Service/Utility Lines (includes power/hydro transmission lines)

Material first ignited (43) Electrical Wiring Insulation

Ignited fuel (04) Electricity

Method of Fire Control (1) Extinguished by fire department

Water (2) Hydrant within 150 to 300 meters

Est. \$ loss (property + contents) \$500,000.00

Control Time 2022/08/18 13:27:30

Ext. agent app. or defer time 2022/08/18 11:50:25

Extinguishing Agent Not Required

Fire Suppression Factors

### Civilian Details for Fires / Explosions

#### Rescues

Children (Under 16) 0

Physical Condition (99) Undetermined

Adults (16-64) 0

Seniors (65+) 0

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

## Structure Details for Fire / Explosions

Building status	(01) Normal (no change)		
Occupancy status	(1) Permanent - Person(s) Present		
Complex	(03) Apartment		
Occupant Type	(2) Renter (business or residential, exc students)		
Illegal Building Use	(8) Not applicable		
Age of Structure	(4) 1971 to 2000 (recent)		
Initial Detection	(2) Fire alarm system sounded		
Extent of Fire	(2) Confined to part of room/area of origin		
Smoke Spread	(7) Spread to other floors, confined to building		
Possible Business Impact	(3) May resume operations within a month		
Est # of Persons Displaced	32 Persons		
Building Height (stories)	44	Stories Below Grade	
Level of Origin	(042) 42nd Floor	Below Grade	<input type="checkbox"/>

## Alarm / Detection / Suppression device Details

### Smoke Alarm at Fire Origin

Alarm Type	(4) Interconnected
Presence/Operation	(2) Floor/suite of fire origin: Smoke alarm present and operated
Alarm Failure	(98) Not applicable: Alarm operated OR presence/operation undetermined

### Smoke Alarm on Other Floors

Presence/Operation	(2) Other floor(s): Smoke alarm present and operated
Presence on Every Level	(1) Yes operational alarms on every level

### Alarm Impact on Persons Evacuating

Impact on Evacuation	(1) All persons (at risk of injury) self evacuated as a result of hearing alarm
# Self Evacuated	Undetermined

### Fire Alarm System

Presence	(1) Fire alarm system present
Operation	(1) Fire alarm system operated
Impact on Evacuation	(1) All persons (at risk of injury) evacuated as a result of hearing fire alarm system

### Sprinkler System

Presence	(2) Partial sprinkler system present
Operation	(2) Did not activate: remote from fire

## Insurance Information for Fires / Explosions

Insurance Est.	(9) Undetermined	Est. Value	(99) Undetermined
----------------	------------------	------------	-------------------

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

## TFS vehicles dispatched to scene: Apparatus / Crew members

Apparatus	<b>A322</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	3
Dispatch time	2022/08/18 11:18:08	En route time	2022/08/18 11:20:03	Arrival time	2022/08/18 11:25:14
Clear time	2022/08/18 14:51:39	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
CORRADETTI, Paolo	CAPT
BIKAS, George	FF1
KOPYLOV, VADYM	FF3

Apparatus	<b>C32</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	2
Dispatch time	2022/08/18 11:18:08	En route time	2022/08/18 11:20:36	Arrival time	2022/08/18 11:33:19
Clear time	2022/08/18 16:28:49	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
KITSCO, John	ACTDC
FILTSOS, Gregory	FF1

Apparatus	<b>P322</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:18:08	En route time	2022/08/18 11:18:39	Arrival time	2022/08/18 11:26:41
Clear time	2022/08/18 14:54:19	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
BROWN, Kevin	CAPT
NEUWALD, ANDREW	FF1
WRIGHT, COLIN	FF1
TROTTIER, TREVOR	FF3

Apparatus	<b>R321</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:18:08	En route time	2022/08/18 11:19:45	Arrival time	2022/08/18 11:25:43
Clear time	2022/08/18 15:12:25	Cancelled en route	No		
Hydrant location					
Actions taken					

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Name	Rank
DE BORST, Robbert	CAPT
CARRUTHERS, KIRSTYN	FF1
HARPER, JEFFREY	FF1
SMITH, John Ryan	FF1

Apparatus	<b>P125</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:18:09	En route time	2022/08/18 11:19:10	Arrival time	2022/08/18 11:37:07
Clear time	2022/08/18 14:41:16	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
WALLACE, Robert	CAPT
BLOXAM, Daniel	FF1
CARRILLO, KENNY	FF3
MUSCHETTE, MATTHEW	FFP

Apparatus	<b>S313</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:25:06	En route time	2022/08/18 11:27:20	Arrival time	2022/08/18 11:34:10
Clear time	2022/08/18 13:58:50	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
MARKHAM, Chris	CAPT
CALDWELL, BRANDON	FF1
FORGET, LUKE	FF1
GUTHENBERG, STEFAN	FF1

Apparatus	<b>LA333</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	2
Dispatch time	2022/08/18 11:31:53	En route time	2022/08/18 11:32:39	Arrival time	2022/08/18 11:50:18
Clear time	2022/08/18 14:46:51	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
NAGLE, David	CAPT
WAGG, Ryan	FF1

Apparatus	<b>R325</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:31:53	En route time	2022/08/18 11:33:17	Arrival time	2022/08/18 11:43:16
Clear time	2022/08/18 13:52:06	Cancelled en route	No		

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>			
HUNTER, Jon		CAPT			
BELOKUROVA, EVGENIA		FF1			
BETLEM, ERIK		FF1			
THOMAS, DERVENT		FF1			
Apparatus	<b>A125</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:31:54	En route time	2022/08/18 11:32:45	Arrival time	2022/08/18 11:38:43
Clear time	2022/08/18 14:58:28	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>			
HORN, Darren		CAPT			
JAVAHERI, Mohammad		FF1			
RUBIN, MIKI		FF1			
CHYZ, CASSANDRA		FF3			
Apparatus	<b>R224</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:31:54	En route time	2022/08/18 11:32:51	Arrival time	2022/08/18 11:39:40
Clear time	2022/08/18 13:57:51	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>			
HOEFT, ERIC		CAPT			
DRISCOLL, Dan		FF1			
PESTANO, CRAIG		FF1			
PYNE, Adam		FF1			
Apparatus	<b>CMD30</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	1
Dispatch time	2022/08/18 11:33:40	En route time	2022/08/18 11:36:09	Arrival time	2022/08/18 11:58:16
Clear time	2022/08/18 22:37:59	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>			
ZIMMERMANN, Adam		FF1			
Apparatus	<b>C31</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	2
Dispatch time	2022/08/18 11:33:51	En route time	2022/08/18 11:35:15	Arrival time	2022/08/18 11:52:03

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Clear time	2022/08/18 14:17:58	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
WALSH, Mike	DC				
STEVENS, JESSE	FF2				
Apparatus	<b>HR332</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:33:51	En route time	2022/08/18 11:34:07	Arrival time	2022/08/18 11:49:50
Clear time	2022/08/18 14:25:26	Cancelled en route	No		
Hydrant location					
Actions taken	(51) Ventilate				
<b>Name</b>	<b>Rank</b>				
WEST, David	CAPT				
MOZAFARI, ASHKAN	FF1				
MARCHAND, JOSHUA	FF2				
PARKIN, BENJAMIN	FF2				
Apparatus	<b>HZ326</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:33:51	En route time	2022/08/18 11:36:00	Arrival time	2022/08/18 11:40:44
Clear time	2022/08/18 14:12:24	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
HARA, Peter	CAPT				
BARRASS, JOHN	FF1				
POCHADT, Ralph	FF1				
ROBINSON, David	FF1				
Apparatus	<b>P221</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:33:51	En route time	2022/08/18 11:34:31	Arrival time	2022/08/18 11:46:51
Clear time	2022/08/18 14:13:18	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
HUBBARD, Nathan	CAPT				
COE, Todd	FF1				
JOHNSTON, MADISON	FF1				
FLANNIGAN, KRISTA	FFP				

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Apparatus	<b>P222</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:33:51	En route time	2022/08/18 11:35:59	Arrival time	2022/08/18 11:44:32
Clear time	2022/08/18 14:00:02	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>		<b>Actions taken</b>	
GAGLIARDI, Frank		CAPT		(00) Action taken, other	
HANNAH, ERIC		FF1		(21) Search	
MEYERS, SEAN		FF1		(21) Search	
PANTEA, ADRIAN		FF3		(21) Search	
Apparatus	<b>P323</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 11:33:51	En route time	2022/08/18 11:35:15	Arrival time	2022/08/18 11:42:02
Clear time	2022/08/18 13:49:06	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>			
CHAPMAN, Paul		CAPT			
GARBER, PAUL		FF1			
HUTTON, TIMOTHY		FF1			
TAGG, JUSTIN		FF1			
Apparatus	<b>C30</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	1
Dispatch time	2022/08/18 11:33:54	En route time	2022/08/18 11:36:40	Arrival time	2022/08/18 11:55:18
Clear time	2022/08/18 22:37:59	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>		<b>Rank</b>			
VERHAEGHE, Thomas		ACTPC			
Apparatus	<b>P311</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:03:00	En route time	2022/08/18 12:05:02	Arrival time	2022/08/18 12:16:16
Clear time	2022/08/18 14:06:42	Cancelled en route	No		
Hydrant location					
Actions taken					

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Name	Rank
MCCULLAGH, Paul Thomas	CAPT
CARPE, John	FF1
DUNN, MATTHEW	FF1
THOMPSON, Lee	FF1

Apparatus	<b>P324</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:03:00	En route time	2022/08/18 12:05:06	Arrival time	2022/08/18 12:12:53
Clear time	2022/08/18 13:52:55	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
TADESON, Rob	CAPT
MORRIS, SHAWN	FF1
PETT, JEREMY	FF1
PLUMMER, ADAM	FF1

Apparatus	<b>P333</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:03:00	En route time	2022/08/18 12:04:10	Arrival time	2022/08/18 12:16:26
Clear time	2022/08/18 13:41:07	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
MERRIFIELD, DAVID	CAPT
REYES, Julian	FF1
HALL, NICHOLAS	FF3
KHAN, IMTIAZ	FF3

Apparatus	<b>T333</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:03:00	En route time	2022/08/18 12:05:05	Arrival time	2022/08/18 12:16:51
Clear time	2022/08/18 14:20:55	Cancelled en route	No		
Hydrant location					
Actions taken					

Name	Rank
WILCOX, Dave	CAPT
LOW, JUSTIN	FF1
MACISAAC, DAVID	FF1
VAUGHAN, ANDREW	FF1

Apparatus	<b>A221</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	3
Dispatch time	2022/08/18 12:03:01	En route time	2022/08/18 12:03:52	Arrival time	2022/08/18 12:16:45

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Clear time	2022/08/18 13:29:26	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
TACKOOR, DES K	CAPT				
REINHARD, ADAM	FF1				
SARTA, JOSHUA	FF1				
Apparatus	<b>C22</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	3
Dispatch time	2022/08/18 12:03:01	En route time	2022/08/18 12:04:24	Arrival time	2022/08/18 12:17:54
Clear time	2022/08/18 14:18:14	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
PARK, Jeff	ACTCAPT				
DRIMMIE, John	ACTDC				
SLENYS, Daina	FF1				
Apparatus	<b>P121</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:03:01	En route time	2022/08/18 12:05:05	Arrival time	2022/08/18 12:30:31
Clear time	2022/08/18 13:50:18	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
GILCHRIST, Greg	CAPT				
EASBY, DYLAN	FF1				
FLEMING, Chris	FF1				
HEACOCK, KEVIN	FF1				
Apparatus	<b>P226</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:03:01	En route time	2022/08/18 12:04:24	Arrival time	2022/08/18 12:17:04
Clear time	2022/08/18 13:45:53	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
ZINSER, Michael	CAPT				
BOJDA, BRAD	FF1				
HUNKA, ROBIN	FF1				
MASTERTON, TIMMOTHY	FF1				

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Apparatus	<b>C10</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	1
Dispatch time	2022/08/18 12:06:00	En route time	2022/08/18 12:06:02	Arrival time	2022/08/18 12:50:05
Clear time	2022/08/18 13:37:41	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
HODGSON, Bradley	PC				
Apparatus	<b>LA231</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	2
Dispatch time	2022/08/18 12:07:24	En route time	2022/08/18 12:08:46	Arrival time	2022/08/18 12:27:37
Clear time	2022/08/18 14:06:20	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
DRAPER, Gene	CAPT				
BASTOS, ARTUR	FF1				
Apparatus	<b>C6</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	0
Dispatch time	2022/08/18 12:10:38	En route time	2022/08/18 12:10:43	Arrival time	2022/08/18 12:35:18
Clear time	2022/08/18 22:26:59	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
Apparatus	<b>HR114</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 12:16:51	En route time	2022/08/18 12:17:59	Arrival time	2022/08/18 12:34:59
Clear time	2022/08/18 14:47:00	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
L'ARCHEVEQUE, JF	CAPT				
BIRKETT, RICHARD	FF1				
FRIAS, DANIEL	FF1				
MCBAY, Daryl	FF1				
Apparatus	<b>C7</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	0
Dispatch time	2022/08/18 12:31:15	En route time	2022/08/18 12:31:27	Arrival time	2022/08/18 12:31:29
Clear time	2022/08/18 14:07:55	Cancelled en route	No		

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
Apparatus	<b>P227</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 14:47:26	En route time	2022/08/18 14:47:42	Arrival time	2022/08/18 14:57:56
Clear time	2022/08/18 17:28:26	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
ROCCASALVO, Peter	CAPT				
GAINER, SAM	FF1				
MCINTYRE, Roger	FF1				
QUIGG, JEFFREY F	FF1				
Apparatus	<b>P131</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 15:23:00	En route time	2022/08/18 15:24:11	Arrival time	2022/08/18 15:42:17
Clear time	2022/08/18 19:19:45	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
MCMILLAN, Vaughan	CAPT				
DAVENPORT, DREW	FF1				
GOULDING, BRADLEY	FF1				
HARIPKO, ORI	FF1				
Apparatus	<b>FI8</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	0
Dispatch time	2022/08/18 15:54:58	En route time	2022/08/18 15:55:06	Arrival time	2022/08/18 16:50:25
Clear time	2022/08/18 22:10:19	Cancelled en route	No		
Hydrant location					
Actions taken					
<b>Name</b>	<b>Rank</b>				
Apparatus	<b>P233</b>	First Arriving at scene	<input type="checkbox"/>	Nr. of personnel	4
Dispatch time	2022/08/18 18:23:08	En route time	2022/08/18 18:27:55	Arrival time	2022/08/18 18:51:15
Clear time	2022/08/18 21:56:44	Cancelled en route	No		
Hydrant location					

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

## Actions taken

Name	Rank
MCDONALD, Tim	CAPT
BOJDA, DREW	FF1
BYLES, BRENT	FF1
TREVENA SMITH, JEROME	FF1

## All Emergency Responses - Officer's Report

### Narrative type - Incident

Narrative ID A125 - Required 1

Last Name HORN First Name Darren Rank CAPT

Author:HORN, Darren 2022/08/18 16:18:27

Was designated Ventilation sector officer.

Smoke migration was coming from elevator as well as the west stairwell which was used for fire attack, and had contaminated floors 33 - 44, mild to moderate smoke on lower levels, and much greater density closer to the fire floor. due to the large volume of smoke that needed to be moved, was assigned a separate TAC channel.

There was minor confusing with which stairwell was east and west, and what stair well had the hatch location. Once that was determined removal of smoke on effected floors went smoothly with crews coordinating well.

We pressurized the stairwells, and used fans on the floors to assist the removal of smoke out of the east stair well hatch, and systematically removed smoke from the building until clear of smoke.

Once task was completed was cleared by IC

Narrative ID A221 - Required 1

Last Name TACKOOR First Name DES K Rank CAPT

Author:TACKOOR, DES K 2022/08/18 14:49:04

A221 stood by, no tasks assigned.

Narrative ID A322 - Required 1

Last Name CORRADETTI First Name Paolo Rank CAPT

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author:CORRADETTI, Paolo 2022/08/18 20:09:26

At 1117 hours on Thursday August 18, 2022 we were dispatched to a fire. Thirty-five units were assigned to this incident. One person responded. The incident occurred at 95 THORNCLIFFE PARK Dr, EY in Ward 15. The local station is 322. The general description of this property is Multi-Unit Dwelling - Over 12 Units. The primary task(s) performed at the scene by responding personnel was extinguishment. No mutual/automatic aid was given or received.

The building was normal. "Mechanical/Electrical Services Room" best describes the primary use of the room or space where the fire originated. This building has forty-four stories above ground. The cause of the ignition was electrical failure. The use, or purpose of the material that was first ignited was "electrical wiring insulation".

The estimated property loss on this incident was \$500,000.

One patient was involved with this incident. One civilian casualty was associated with this incident.

Alarm number F22109549 has been assigned to this incident.

On arrival A322 had reports of smoke on multiple floors including 26,36,39 and 41 as well as a report of a fire in the rooftop mechanical room with floor 42,43 and 44 indicated on the annunciator panel. R321 was tasked to investigate the basement compactor room.

A322 proceeded to the 41st floor with two members of P322, par 4.

Elevator control was established and there was light smoke visible on the 41st floor.

A322 proceeded up the west stairwell and found heavy smoke on the 42nd floor, a working fire was announced. A322 quickly checked the 43rd floor and it was clear. A322 crew started setting up the 65mm highrise hose while A322 Captain and P322 crew search for the seat of the fire on the 42nd floor.

Fire was located on the 42nd east electrical closet, flames and arching from wires and electrical components. A dry chem extinguisher was utilized from the hose cabinet and the fire knocked down for a few moments until it started arching again. A322 proceeded to the 43rd floor to get two more dry chem extinguishers. Command was requested to have the power cut to this location.

The extinguishers were deployed and S313 had extended the line to the electrical cabinet. A322 was low on air and left to change cylinders.

Assisted with taking cylinders to 37 and a stood by for reassignment.

**Narrative ID** C10

**Last Name** HODGSON

**First Name** Bradley

**Rank** PC

Author:HODGSON, Bradley 2022/08/18 17:12:09

C10 assumed the role as Command Post Officer.

When the fire was knocked down and ventilation was almost completed, C10 was cleared by the Incident Commander. No further tasks.

**Narrative ID** C30

**Last Name** VERHAEGHE

**First Name** Thomas

**Rank** PC

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author: VERHAEGHE, Thomas 2022/08/19 01:21:32

C30 was notified by TFS communications of a working fire response to 95 Thorncliffe Park drive. Due to the building being a high rise with heavy smoke I asked TFS communications to increase alarm level to a second alarm. C30 monitored the call via radio to arrival. A face to face update was received by C32 and C30 assumed command of the incident. Due to heavy smoke migration through out the building a third alarm was requested. C31 was assigned forward staging officer on the 37th floor. C32 was assigned ground floor logistics officer and C22 assigned incident safety officer. C10 assumed role of command post officer.

Primary and secondary searches were completed. Entry control and RIT were also established. Electrical fire in 42nd floor electrical panel\ closet was extinguished with numerous CO2 extinguishers.

Ventilation of smoke took approximately 2 hours to clear due to large volume.

One resident transported to hospital by EMS for minor smoke inhalation and was later released.

Divisional Commander Darling and Denysek responded for support. Commander Darling remained on scene for entire incident to co-ordinated with building staff and support I\C. Fire investigator Sarah Jessop investigated and liased with building staff, alarm tech, and electricians. Division Chief Steve Wilson responded to confirm life safety systems in building were appropriate. Chief Pegg responded as well.

Building managemnet organized accommodations for residents of the 42nd floor and were instrumental in looking after the building residents.

Prior to TFS clearing the fire alarm system was operating and elevators were reset. A fire watch was established by building management with approximately 20 security guards. Restoration team on site for clean up.

Building turned over to building management.

Narrative ID C6

Last Name DARLING

First Name Steven

Rank DCOM

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author: DARLING, Steven 2022/08/21 08:56:35

Chief 6 responded to this 44 story highrise residential fire on the 3rd Alarm. The Incident Commander was Chief 30, A/PC Thomas Verhaeghe who had established Thorncliffe Command in the Command vehicle prior to my arrival.

All relevant sectors were in place and the fire was under control upon my arrival with crews in the process of conducting overhaul and ventilation. There was a significant amount of smoke throughout the building so crews had instructed the residents through the EVAC system, to shelter in place if it was safe to do so.

Primary and Secondary searches had been complete prior to my arrival with 1 resident having been transported to Michael Garron Hospital by Toronto Paramedic Services with minor smoke inhalation and released that same evening.

The power to the entire east side of the building from Floors 24-44 were without power as a result of the fire in the electrical panel on the 42nd floor.

I met with the buildings Regional General Manager-Moreland Properties Susan Morasse along with other members of her team to co-ordinate a plan to house any displaced residents. We establish a temporary location in a "Party Room" equipped with air conditioning and washrooms. Building management also provided food and water for the residents of 95 Thorncliffe Pk Dr.

C6 established a Joint Command with Toronto Police, Toronto Paramedics, Building officials, Electricians and building Restoration/Maintenance and conducted hourly Business Cycle meetings throughout the incident.

C6 met with the Office of Emergency Management team and Building Management via phone conference to co-ordinate and plan the temporary relocation of the occupants from the 42nd floor who would not be permitted to return to their units until clean-up and restoration was complete as per their Environmental Engineer. Temporary housing was located by Building Management at the various Marriott Hotels in the GTA and rooms for another 50 were secured if required.

After electricians completed their assessment of the damage to the electrical system, they developed an electrical repair strategy that was approved by ESA rep Ben Demassi. Using this strategy, electricians believe they can restore power to the building as follows:

Floors 24-36 possibly within 24hrs  
Floors 36-39 possibly 72 hrs  
Floors 40-44 possibly 7 days

We had confirmation by building maintenance that all units had domestic water and fire pumps were operational for the fire suppression system. There was problems resetting the fire alarm system but Trace Fire Protection was able to get the system operational and restore full function of all the elevators.

As a result of the electrical repair plan, stairwell doors were required to be left open. Building management contracted a security company to conduct fire watch until the doors could be kept closed as per the Ontario Fire Code.

Building Management communicated instructions and updates to residents through their internal, on-line messaging system for those who had power and via written notification for those without, which was delivered by security to each of the affected units. Battery operated smoke detectors and portable lights were purchased and distributed by building management to each unit that was affected, to ensure in-suite fire detection during the power outage.

Once I was satisfied that all safety concerns were addressed, the building was returned to the Building Management and Toronto Fire Services cleared the scene. TFS will continue to follow up with the progress of the repairs.

Narrative ID Car 32

Last Name KITSCO

First Name John

Rank DC

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author:KITSKO, John 2022/08/18 21:31:12

C32 was dispatched "on the air" to 95 Thornecliff Park Drive, a multi-storey highrise residential, on a first alarm fire response for the report of a fire. Upon arrival, C32 completed a 360 and requested an update from the first incoming apparatus. At this time C32 assumed command, with command designation Thorncliffe Command. With a second alarm already requested, C32 expanded IMS by designating crews, including, Fire Floor Sector, Ventilation Sector, Staging and Base. IRIT, Rehab and Decon were established, and ensured all sector officer benchmarks were completed and announced. C32 utilized all Second Alarm personnel to complete all required tactical objectives. At this time, command was transferred to PC30, who promptly requested a Third Alarm response, and C32 was designated Ground Sector Officer. Ground sector responsibilities included providing sufficient resources to all sectors, including C31, Forward Sector. C32 remained on scene and assisted in the liaison with utilities, building representatives and required personnel to provide tenants with logistical support. C32 was cleared by PC30.

**Narrative ID** HR114 - Required 1

**Last Name** L'ARCHEVEQUE **First Name** JF **Rank** CAPT

Author:L'ARCHEVEQUE, JF 2022/08/18 15:40:21

HR114 was dispatched to a 2nd Alarm Fire at 95 Thorncliffe Park Dr on channel South Tac2. On arrival, Command directed HR114 crew to support HR332 crew for Ventilation. HR114 Captain monitored channel South Tac4 for the Vent Sector Officer channel. HR114 crew brought up the cart with multiple Electric PPVs to the Fire floor (42nd floor). Three PPVs were ventilating the floor towards the East Stairwell where the top hatch was opened. Two LED lights was used to illuminate the 42nd floor. The task started with medium smoke and was clear couple hours later. After three hours, Command cleared HR114 from this call. After a quick rehab and a change of SCBA bottles, HR114 cleared and returned to station 114.

**Narrative ID** HR332 - Required 1

**Last Name** WEST **First Name** David **Rank** CAPT

Author:WEST, David 2022/08/18 16:51:03

HR332 crew moved forward with 2 FST X-tinguishers to assist with fire control. On arrival on the 42nd floor the fire was out and there was no need to deploy them. HR332 used our cart to shuttle air bottles to staging on the 37th floor. HR332 gas and electric fan used to assist with ventilation.

**Narrative ID** HZ326 - Required 1

**Last Name** HARA **First Name** Peter **Rank** CAPT

Author:HARA, Peter 2022/08/18 14:57:46

Has326 assisted A125 with ventilation operations which included managing PPV in both the E and W stairwells and with systematic removal of smoke from upper floor levels. Haz 326 shuttled bottles from the lobby to the 37th floor. Haz 326 assumed Vent Sector Officer at 12:50 to relieve A125. Haz 326 relinquished Vent Sector Officer back to A125 at 12:52. Haz326 did a systematic search in both stairwells for occupants and smoke conditions. Haz326 changed bottles and cleared shortly following.

**Narrative ID** LA231 - Required 1

**Last Name** DRAPER **First Name** Gene **Rank** CAPT

Author:DRAPER, Gene 2022/08/18 16:16:21

Arrived and assisted AL333 with scba cylinder deliveries. Supplied extra drinking water for crews. Left AL333 with a supply of SCBA cylinders and took as many empties as we could upon being cleared.

**Narrative ID** LA333 - Required 1

**Last Name** NAGLE **First Name** David **Rank** CAPT

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author:NAGLE, David 2022/08/18 20:22:18  
LA333 supplied crews with full air cylinders, a few extinguishers and plenty of fresh water.  
LA333 cleared by IC, after confirming that no new bottle changes were required.

**Narrative ID** P121 - Required 1

**Last Name** GILCHRIST **First Name** Greg **Rank** CAPT

Author:GILCHRIST, Greg 2022/08/18 18:13:39  
P121 captain was rehab sector officer.

**Narrative ID** P125 - Required 1

**Last Name** WALLACE **First Name** Robert **Rank** CAPT

Author:WALLACE, Robert 2022/08/18 17:54:59

P125 arrived 4th in on the first alarm and I announced and moved forward to lobby for assignment.

After elevator control took the first 2 crews up we then went up via elevator to the 40th

We brought up some dry chem extinguishers and handed them off to the fire attack crews.

Awaiting assignment and with the radio traffic we starting checking smoke conditions on the floors below and had a bottle change on the 37th fl.

We were tasked with checking unit [REDACTED] where there was a family off 3 including an expecting mother  
The father wanted scba's supplied to the family and I told him that that couldn't happen and that they were safe if they stayed in their unit as it was smoke free and they had their windows open.  
As we ascended we helped some more civilians down the evacuation stairwell.

We were asked by civilians to check 2 more apartments on the 27th and 21st floor.

We then continued down to ground floor as it was time for another bottle change and rehab.

After rehab P125 crew went up to 42 and 37 and helped gather equipment and bring it down in the elevator

P125 was cleared by command.

**Narrative ID** P131 - Required 1

**Last Name** MCMILLAN **First Name** Vaughan **Rank** CAPT

Author:MCMILLAN, Vaughan 2022/08/18 20:01:41

P131 arrived and relieved P227.

P131 shuttled residents in the elevators from the ground floor to the 44th floor.

P131 was relieved by another crew and cleared the call.

**Narrative ID** P221 - Required 1

**Last Name** HUBBARD **First Name** Nathan **Rank** CAPT

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author:HUBBARD, Nathan 2022/08/18 18:21:42

P221 was part of the 2nd alarm response.

P221 was tasked with primary search of the 42, 43 & 44th floor hallways. P221 brought CO & Dry Chem extinguishers and air bottles when heading to staging on the 37th floor via elevator. P221 was accompanied by P222 crew, P221 & P222 dropped equipment and searched the three assigned hallways. The hallways were clear.

P221 was then tasked to help Vent Sector ventilate the building floor by floor. P221 was assigned to go to the roof and open and confirm where the roof hatch was. P221 had to force a door open in the east stairwell for smoke egress. P221 & P222 then went floor by floor to assist. When all floors were clear and several air bottles were empty, P221 & P222 crew went to rehab.

P221 was cleared shortly after by C32

Damaged -  
East Stairwell top floor outside door (outside mechanical room) - no keys were available

**Narrative ID** P222 - Required 1

**Last Name** GAGLIARDI **First Name** Frank **Rank** CAPT

Author:GAGLIARDI, Frank 2022/08/18 15:15:43

We arrived first apparatus on the second alarm and established base sector. I was assigned base sector officer and P222 crew moved forward with P221 to conduct a secondary search and assist with ventilation.

**Narrative ID** P226 - Required 1

**Last Name** ZINSER **First Name** Michael **Rank** CAPT

Author:ZINSER, Michael 2022/08/18 16:15:39

Escorted electrical crews to the roof to shut down power to the fire floor.

**Narrative ID** P227 - Required 1

**Last Name** ROCCASALVO **First Name** Peter **Rank** CAPT

Author:ROCCASALVO, Peter 2022/08/18 19:14:07

P227 crew was given the task to take over elevator control for the floor 24 to floor 44. Also had elevator control for ground floor to floor 23. As requested by Chief 30 crew members began shuttling tenants to floors below the fire floor.

**Narrative ID** P233 - Required 1

**Last Name** MCDONALD **First Name** Tim **Rank** CAPT

Author:MCDONALD, Tim 2022/08/18 22:16:23

P233 arrived on scene and where tasked with elevator control.  
Two P233 firefighters shuttled residents to and from their floors while the alarm system was active.  
P233 cleared by command and returned to station.

**Narrative ID** P311 - Required 1

**Last Name** MCCULLAGH **First Name** Paul Thomas **Rank** CAPT

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author:MCCULLAGH, Paul Thomas 2022/08/18 17:54:01  
P 311 Tasks.  
Secondary Search.  
41st  
42nd  
43rd  
44th Floors.  
All Clear  
Changed Cylinders and then Cleared by Chief 32.

**Narrative ID** P322 - Required 1

**Last Name** BROWN **First Name** Kevin **Rank** CAPT

Author:BROWN, Kevin 2022/08/18 20:16:08

P322 was third truck in. I assumed lobby control. One of my firefighters was assigned elevator control and the other joined A322. Announcements were made. Myself and two firefighters set up entry control. I coordinated with building staff with getting the power shut off. We continue with entry control. Announcements were made through out the incident. P322 assisted with clean up and was cleared by command. Exposure reports were completed for the entire crew.

**Narrative ID** P323 - Required 1

**Last Name** CHAPMAN **First Name** Paul **Rank** CAPT

Author:CHAPMAN, Paul 2022/08/18 15:30:44

P323 arrived and moved forward par 4. P323 was tasked with taking an additional PPV up to the fire floor. Once on the fire floor there were multiple trucks assigned to ventilation so P323 took the task on to check smoke conditions on the floors below the fire floor. P323 checked from floor 35 descending to floor 22. Once at 22 we took on the task to escort two occupants down to the lobby and outside. Once outside P323 captain gave an update to command and went to Air Light to change our bottles and wait to be given another task. P323 was cleared by command shortly after.

**Narrative ID** P324 - Required 1

**Last Name** TADESON **First Name** Rob **Rank** CAPT

Author:TADESON, Rob 2022/08/18 14:40:48

-responded to and checked in with Base officer P222 Captain  
-sent forward to shuttle air bottles to the 37th floor  
-assisted with breaking down the 65mm hose lines

**Narrative ID** P333 - Required 1

**Last Name** MERRIFIELD **First Name** DAVID **Rank** CAPT

Author:MERRIFIELD, DAVID 2022/08/18 14:18:14

P333 checked in on unit [REDACTED]. A [REDACTED] pregnant woman was anxious because of the fire. P333 assessed the patient. She was not exposed to the smoke. Smoke conditions on the floor and unit were clear. There was an odor of electrical burning. The woman had no injuries, pain or discomfort. The patient decided she did not want to go to the hospital or see EMS. P333 spent some time reassuring her which had a positive effect. The family wanted to continue their shelter in place. She was advised to call 911 if anything changed.

The family in unit [REDACTED] wanted to evacuate the building. There was a family of 7 with young children. P333 crew assisted them to Elevator Control and the family was safely moved to the lobby.

**Narrative ID** R224 - Required 1

**Last Name** HOEFT **First Name** ERIC **Rank** CAPT

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Author:HOEFT, ERIC 2022/08/18 19:04:23  
R224 arrived and our first task was a medical check call in apartment 4606.  
R224 next task was RIT. Remained as RIT until cleared by command.

**Narrative ID** R321 - Required 1

**Last Name** DE BORST

**First Name** Robbert

**Rank** CAPT

Author:DE BORST, Robbert 2022/08/18 17:27:16

R321 arrived second on scene and moved forward to backup A322.

R321 investigated the garbage room on B1 for a possible fire.

B1 and garbage room all clear.

R321 proceed to the roof top to investigate conditions.

Roof and secondary roof level all clear.

R321 accessed roof door panel on the south east side for ventilation.

R321 proceeded to floor 42 and met with A322.

Electrical room that was on fire was adjacent to apartment [REDACTED].

After A322 applied agent, R321 had a temperature reading of 210 degrees on the panel.

R321 proceed down the stairs to investigate smoke conditions and to assist several residences evacuating.

Floors 44 to 42 had heavy smoke. Floors 41 to 10 had moderate smoke. Floors 9 to ground floor had clear smoke conditions.

R321 was cleared by IC.

**Narrative ID** R325 - Required 1

**Last Name** HUNTER

**First Name** Jon

**Rank** CAPT

Author:HUNTER, Jon 2022/08/18 14:59:17  
R325 was dispatched on the working fire.

Upon arrival R325 crew par 3 moved forward with 3 x CO2 extinguishers, while R325 captain was assigned staging officer on the 41st floor.

floors 38-41 had moderate to heavy smoke conditions so R325 moved staging location to the 37th floor and communicated the move to command.

R325 Capt coordinated with command to have SCBA cylinders staged on the 37 floor so crews could exchange bottles.

R325 captain was relieved by C31 as staging officer after a face to face handover.

R325 crew (par 3) was assigned to the fire floor and used 3 x CO2 extinguishers on the electrical fire before being relieved.

R325 (par 4) changed air bottles and was assigned to check smoke conditions on the fire floor and conduct a secondary search. Secondary search complete and all clear. Light smoke persisted on the fire floor.

R325 was then cleared by command

**Narrative ID** S313 - Required 1

# EMERGENCY INCIDENT REPORT

Incident Number: **F22109549**

Exposure: **000**

continued...

Last Name MARKHAM First Name Chris Rank CAPT

Author:MARKHAM, Chris 2022/08/18 17:44:08

S313 arrived at address and was immediately tasked as both iRIT and to lengthen first in crews line by 2 lengths.S313 split up into two teams of 2 and completed both tasks.RIT then arrived and S313 returned to PAR 4 status.

S313 then used 4-5 CO2 extinguishers on the fire which darkened down until no more visible flames were showing from the electrical closet on the 42nd floor.S313 was tasked multiple times to return to fire floor with more extinguishers.After thoroughly checking the location of the fire with the TIC, no more heat signatures were present.S313 was then sent to Re-Hab and then cleared by Command.

Narrative ID T333 - Required 1

Last Name WILCOX First Name Dave Rank CAPT

Author:WILCOX, Dave 2022/08/18 17:20:00

T333 respond on the third alarm and was task with ventilation

T333 Captain report to Ventilation Sector Officer

T333 crew set up two PPV on floors 37, 38 ,39 40 ,41

T333 crew also set up PPV on first floor of west stairwell

T333 Captain check on smoke conditions from 37 floor to top of building and ensure all smoke was removed

T333 report to rehab

T333 clear by command after rehab

## Narrative type - Company

Narrative ID C31

Last Name WALSH First Name Mike Rank DC

Author:WALSH, Mike 2022/08/18 15:32:43

C31 was deployed to be Staging Officer on 41st floor. Due to heavy smoke conditions, staging was re-located to 37 floor.

C31 co-ordinated with Command to dispatch crews, cylinders, ventilation and fire condition updates.

Fire was knocked down and loss stopped and C31 cleared.

## Authorization

### Member making report

Last name	First name	Rank	Date	Completed
CORRADETTI	Paolo	CAPT	2022/08/19 01:59:56	<input checked="" type="checkbox"/>

### Officer in charge

Last name	First name	Rank	Date
VERHAEGHE	Thomas	PC	2022/08/19 02:00:00

### Reviewed by

Last name	First name	Rank	Date	Approved
DARLING	Steven	PC	2022/08/19 05:39:17	<input checked="" type="checkbox"/>